
Meridian 1

Property Management System Interface

Description

Document Number: 553-2801-101

Document Release: Standard 7.00

Date: August 1996

© 1989, 1996

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules, and the radio interference regulations of Industry Canada. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses and can radiate radio frequency energy, and if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at their own expense.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

August 1996

Standard, Release 7.00. This document is reissued for X11 Release 22.0x.

December 1994

Standard, Release 6.00. This document is reissued to include editorial changes and indexing. Due to the extent of the changes, revision bars are not used.

August 1993

Standard, Release 5.00. This document is reissued to include updates and changes for X11 Release 19. Updates are indicated by revision bars in the margins.

December 1991

Standard, Release 4.00. This document is issued to include changes and updates for X11 Release 17. Due to the extent of changes, revision bars are omitted.

December 1990

Standard, Release 3.00. This document is reissued to include updates and changes for X11 Release 16. Updates are indicated by revision bars in the margins.

June 1990

Standard, Release 2.00. This document is reissued to include updates and changes for X11 Release 15. Updates are indicated by revision bars in the margins.

December 1989

Standard, Release 1.00. This document is issued to include updates and changes for X11 Release 14.

Contents

Feature description	1
Background Terminal	2
Meridian Hospitality Voice Services	2
PMSI and Meridian 1 messages	3
Types of messages	3
PMS messages sent to the Meridian 1	4
Message Waiting and Do Not Disturb status	5
Automatic control	6
Off Hook Detection	7
Dial Access	8
Call Party Name Display name change	9
Call Number Information messages	10
Meridian 1 messages sent to the PMS	12
Message control and protocols	13
Message protocols	14
Meridian 1 protocol	14
PMS protocol	15
Installation, configuration, and maintenance	19
PMSI link requirements	19
PMSI installation requirements	22
PMSI Set Option commands	22
PMSI Standardization	22

Message transmission	23
Message retransmission	23
Polling	25
Message monitoring	26
X11 Release 17 PMSI configuration	28
X11 Release 18 PMSI configuration	29
X11 Release 19 and later PMSI configuration	29
Configuration prompts for LD 17	30
Configuration commands for LD 37	33
Configuration prompts for LD 22	35
Operating parameters	37
Feature interactions	38
PMSI Standardization recommendations	39

List of figures

Figure 1	
Dedicated RS-232-C connector pins	21

List of tables

Table 1	
Room status commands	4
Table 2	
SPRE dialing commands	8
Table 3	
Meridian 1 messages sent to PMS	12
Table 4	
Message control and special characters	13
Table 5	
X11 Release 17 PMSI configuration	28
Table 6	
X11 Release 18 PMSI configuration	29
Table 7	
X11 Release 19 and later PMSI configuration	30